

1968 OCT 25 21 09Z

OUT 66265

PRESENT ON THE TITLED EDGE OF THE FILM THROUGHOUT THE MISSION.
ROLLER CHATTER FOG PATTERNS ARE PRESENT ALONG THE

ADVANCE CY
SANITIZED
WITH TEXT

SECRET

NON-TITLED EDGE OF THE FILM THROUGHOUT THE MISSION. THESE ROLLER CHATTER FOG PATTERNS ARE AS SEVERE AS MISSION G-046 AND AT TIMES DEGRADE THE IMAGERY.

(2) 9L SIDE: FRAME 5 CONTAINS A 0.2 INCH WIDE FOG PATTERN EXTENDING 7.5 INCHES FROM THE TITLED EDGE INTO THE FORMAT AREA. THIS FOG PATTERN IS PARALLEL TO THE FILM'S MINOR AXIS AND IS 5.7 INCHES FROM THE NON-DATA BLOCK EDGE OF THE FORMAT. TWO MINOR PLUS DENSITY LINES PARALLEL TO THE MAJOR AXIS, 5.15 AND 5.75 INCHES FROM THE TITLED EDGE OF THE FILM, OCCUR INTERMITTENTLY ON FRAMES 875 THRU 1275. FRAMES 1651 THRU 1656 CONTAIN A SERIES OF THREE PLUS DENSITY MARKS PARALLEL TO THE MAJOR AXIS OF THE FILM. EACH MARK HAS ASSOCIATED WITH IT, A PAIR OF MINUS DENSITY MARKS; ONE ON EACH SIDE OF THE PLUS DENSITY LINE. THE MARK LENGTHS VARY FROM 40 TO 17 INCHES AND OCCUR 4.0 TO 5.5 INCHES FROM THE NON-TITLE EDGE OF THE FILM.

(3) BOTH: THE FORMATS OF BOTH 9L AND 9R SIDES, FRAME 0001, CONTAIN A WEAK, SECOND FORMAT GHOST TYPE IMAGE.

D. PHYSICAL DEGRADATIONS:

PAGE 4 RUEADJU 114 S E C R E T

(1) 9R SIDE: A HEAT SPLICE IS PRESENT ON FRAME 1232. A MANUFACTURER'S SPLICE IS PRESENT ON FRAME 1658.

(2) 9L SIDE: A MANUFACTURER'S SPLICE IS PRESENT BETWEEN FRAMES 2234 AND 2235. THERE ARE HEAT SPLICES BETWEEN FRAMES 2113 AND 2114 AND THROUGH FRAME 1276.

E. AUXILIARY DATA: THE EVENTS COUNTER STARTED AT 0000 AND THE FIRST FRAME IS TITLED FRAME 0001. THE EVENTS COUNTER HELD A MINUS ONE BIAS THROUGHOUT THE MISSION. THE EVENTS PORTION OF THE DATA CHAMBER APPEARS SHARPER THAN THE CLOCK PORTION.

F. THE LAST TITLED FRAME ON BOTH SIDES IS 2493, EVENTS NUMBER 2492. THE LAST FRAME CONTAINING IMAGERY IS TITLED FRAME 2492.

4. POSITIVES: THE PRINTING AND PROCESSING WERE GOOD.

GP-1

S E C R E T

END OF MESSAGE